

2009 ACCESSORIES & EQUIPMENT

Interior Trim and Paneling - Cobalt & G5

SPECIFICATIONS

FASTENER TIGHTENING SPECIFICATIONS

Application	Specification	
	Metric	English
Assist Handle Screws	6 N.m	53 lb in
Coat Hook Screw	6 N.m	53 lb in
Sunshade Retainer Screws	6 N.m	53 lb in
Sunshade Screws	6 N.m	53 lb in
Windshield Pillar Trim Screw	2 N.m	18 lb in

REPAIR INSTRUCTIONS

UPPER EXTENSION TRIM PANEL REPLACEMENT




Fig. 1: View Of Upper Extension Trim Panel
Courtesy of GENERAL MOTORS CORP.

Callout	Component Name
Fastener Tightening Specifications: Refer to <u>Fastener Tightening Specifications</u>.	
1	Panel Assembly, Upper Front Side Door Tip: Panel is only serviced on vehicles with manual mirrors.
2	Retainer, Upper Front Side Door Panel

FRONT SIDE DOOR TRIM PANEL REPLACEMENT




Fig. 2: Trim Panel Replacement - Side Front Door
 Courtesy of GENERAL MOTORS CORP.

Callout	Component Name
Fastener Tightening Specifications: Refer to <u>Fastener Tightening Specifications</u> .	
Preliminary Procedures	
1. Remove the upper extension. Refer to <u>Upper Extension Trim Panel Replacement</u> . 2. Remove the armrest pull cup. Refer to <u>Armrest Pull Cup Replacement</u> . 3. Remove the manual window regulator handle if equipped. Refer to <u>Door Window Regulator Handle Replacement</u> . 4. Disconnect the inside door handle cable. Refer to <u>Door Inside Handle Replacement</u> .	
1	Push Pins (Qty: 2)
2	Panel Assembly, Side Door Trim
3	Retainer, Side Door Trim

REAR SIDE DOOR TRIM PANEL REPLACEMENT




Fig. 3: View Of Side Rear Door Trim Panel
 Courtesy of GENERAL MOTORS CORP.

Callout	Component Name
Preliminary Procedures	
1. Remove the armrest pull cup. Refer to <u>Armrest Pull Cup Replacement</u> . 2. Remove the manual window regulator handle if equipped. Refer to <u>Door Window Regulator Handle Replacement</u> . 3. Disconnect the inside door handle cable. Refer to <u>Door Inside Handle Replacement</u> .	
1	Side Door Trim Screw (Qty: 2) CAUTION: Refer to <u>Fastener Caution</u> . Tighten: 2.2 N.m (19 lb in)

2	Side Door Trim Panel Assembly
3	Side Door Trim Retainer

REAR DOOR ENERGY ABSORBER PAD REPLACEMENT




Fig. 4: Energy Absorber Pad Replacement - Rear Door
 Courtesy of GENERAL MOTORS CORP.

Callout	Component Name
Fastener Tightening Specifications: Refer to <u>Fastener Tightening Specifications</u> .	
Preliminary Procedures	
1. Place the window in the full up position. 2. Remove the rear door trim panel. Refer to <u>Rear Side Door Trim Panel Replacement</u> . 3. Remove the rear door water deflector. Refer to <u>Rear Side Door Water Deflector Replacement</u> . 4. Remove the rear door window regulator. Refer to <u>Rear Side Door Window Regulator Replacement (Manual Sedan)</u> or <u>Rear Side Door Window Regulator Replacement (Power Sedan)</u> .	
1	Retainer, Rear Door Energy Absorber Tip: Remove the push-in retainer from the door.
2	Energy Absorber, Rear Door


FRONT SIDE DOOR WATER DEFLECTOR REPLACEMENT

Fig. 5: View Of Front Side Door Water Deflector
Courtesy of GENERAL MOTORS CORP.

Callout	Component Name
Preliminary Procedure: Remove the interior trim panel. Refer to <u>Front Side Door Trim Panel Replacement</u> .	
1	Front Side Door Water Deflector Assembly Tip: Carefully pull the water deflector away from the door while feeding any wiring or connectors through the water deflector.

REAR SIDE DOOR WATER DEFLECTOR REPLACEMENT




Fig. 6: View Of Rear Side Door Water Deflector
Courtesy of GENERAL MOTORS CORP.

Callout	Component Name
Preliminary Procedure: Remove the interior trim panel. Refer to <u>Rear Side Door Trim Panel Replacement</u> .	
1	Rear Side Door Water Deflector Assembly Tip: Carefully pull the water deflector away from the door while feeding any wiring or connectors through the water deflector.

ARMREST PULL CUP REPLACEMENT




Fig. 7: View Of Armrest Pull Cup
 Courtesy of GENERAL MOTORS CORP.

Callout	Component Name
1	Door Panel Pull Cup Trim Plate
2	Door Panel Pull Cup Screw CAUTION: Refer to Fastener Caution . Tighten: 2 N.m (18 lb in)
3	Pull Cup Assembly Tip: Disconnect the electrical connector.

ARMREST BRACKET REPLACEMENT (COUPE)




Fig. 8: Identifying Armrest Bracket (Coupe)
 Courtesy of GENERAL MOTORS CORP.

Callout	Component Name
Preliminary Procedures: Remove the door panel. Refer to <u>Front Side Door Trim Panel Replacement</u> .	
1	Bracket Door Panel Armrest Screw CAUTION: Refer to <u>Fastener Caution</u> . Tighten: 9 N.m (80 lb in)
2	Door Panel Armrest Bracket
3	Door Panel Armrest Clip

ARMREST BRACKET REPLACEMENT (SEDAN)




Fig. 9: Identifying Armrest Bracket (Sedan)

Courtesy of GENERAL MOTORS CORP.

Callout	Component Name
Preliminary Procedures: Remove the door panel. Refer to <u>Front Side Door Trim Panel Replacement</u> .	
1	Bracket Door Panel Armrest Screw CAUTION: Refer to <u>Fastener Caution</u> . Tighten: 9 N.m (80 lb in)
2	Door Panel Armrest Bracket
3	Door Panel Armrest Clip

REAR COMPARTMENT TRIM PANEL REPLACEMENT




Fig. 10: Identifying Rear Compartment Trim Panel
Courtesy of GENERAL MOTORS CORP.

Callout	Component Name
1	Rear Compartment Trim Clip
2	Rear Compartment Trim Panel Assembly Tip: Remove the subwoofer, if equipped.

ASSIST HANDLE REPLACEMENT





Fig. 11: View Of Assist Handle

Courtesy of GENERAL MOTORS CORP.

Callout	Component Name
1	Assist Handle
2	Assist Handle Screw CAUTION: Refer to <u>Fastener Caution</u> . Tighten: 6 N.m (53 lb in)

COAT HOOK REPLACEMENT

**Fig. 12: View Of Coat Hook****Courtesy of GENERAL MOTORS CORP.**

Callout	Component Name
1	Coat Hook
2	Coat Hook Screw CAUTION: Refer to <u>Fastener Caution</u> . Tighten: 6 N.m (53 lb in)

SUNSHADE REPLACEMENT




Fig. 13: Identifying Sunshade Replacement
Courtesy of GENERAL MOTORS CORP.

Callout	Component Name
1	Sunshade Assembly
2	Sunshade Support Screw CAUTION: Refer to <u>Fastener Caution</u> . Tighten: 6 N.m (53 lb in)
3	Sunshade Support Bezel

SUNSHADE RETAINER BEZEL REPLACEMENT

**Thank you very much
for your reading.**

Please Click Here

**Then Get More
Information.**