



The small end bush on this engine cannot be replaced, therefore it is handled by the Parts Department together with the connecting rod.