




Fig. 94: Passenger's Lumbar Circuit, W/ Recaro Front Bucket Seat