

## PRECAUTION




1. Check that the battery cables are connected to the correct terminals.
2. Disconnect the battery cables when the battery is given a quick charge.
3. Do not perform tests with a high voltage insulation resistance tester.
4. Never disconnect the battery while the engine is running.

CHOCK—02

## PREPARATION

### SST (SPECIAL SERVICE TOOLS)

CHOCK—19

|                                                                                     |               |                                               |                                                                |
|-------------------------------------------------------------------------------------|---------------|-----------------------------------------------|----------------------------------------------------------------|
|    | 09285-76010   | Injection Pump Camshaft Bearing Cone Replacer | Rotor rear bearing cover for hi-speed compact type             |
|    | 09286-46011   | Injection Pump Spline Shaft Puller            | Rectifier end frame for hi-speed compact type                  |
|    | 09820-00021   | Alternator Rear Bearing Puller                | Rotor rear bearing for hi-speed compact type                   |
|    | 09820-00030   | Alternator Rear Bearing Replacer              | Rotor rear bearing for hi-speed compact type                   |
|  | 09950-60010   | Replacer Set                                  |                                                                |
|  | (09951-00180) | Replacer 18                                   | Rotor for hi-speed compact type                                |
|  | (09951-00230) | Replacer 23                                   | Rotor front bearing for hi-speed compact type                  |
|  | (09951-00340) | Replacer 34                                   | Oil seal for hi-speed compact type                             |
|  | (09951-00400) | Replacer 40                                   | Rotor front bearing for hi-speed compact type                  |
|  | 09950-70010   | Handle Set                                    |                                                                |
|  | (09951-07100) | Handle 100                                    | Rotor, rotor front bearing, oil seal for hi-speed compact type |