

- DRIVE WHEEL HEAVY ACCELERATION
- OVERINFLATION



- HARD CORNERING
- UNDERINFLATION
- LACK OF ROTATION