

CASTER IS POSITIVE WHEN THE LOAD (LOWER BALL JOINT) IS AHEAD OR PULLING THE SPINDLE.



LOAD IS PULLING THE WHEEL.