

PERSONAL INJURY CAUTION

Appropriate service methods and proper repair procedures are essential for the safe, reliable operation of all motor vehicles, as well as for the personal safety of the person doing the repair. There are many variations in procedures, techniques, tools and parts for servicing vehicles, as well as in the skills of the people doing the work. This manual cannot possibly anticipate all such variations and provide advice or precautions for each. Anyone who deviates from the instructions provided in this manual must ensure their own safety and preserve the safety and integrity of the vehicle. The following list contains general precautions that should always be followed while working on a vehicle.

- *Safety stands are required whenever a procedure calls for under-body work.*
- *Do not smoke when you work on a vehicle.*
- *To prevent serious burns, do not touch any hot metal parts.*
- *Set the parking brake when you work on the vehicle.*
- *Turn the ignition switch OFF unless a procedure states otherwise.*
- *The engine may operate only in a well-ventilated area.*
- *Avoid moving parts when the engine is running.*
- *Safety glasses must be worn for eye protection.*



00000000

We support voluntary technician certification through the National Institute for Automotive Service Excellence.

NUBIRA/LACETTI Service Manual (MY2004)

FOREWORD

This manual includes procedures for maintenance, adjustment, service operations, and removal and installation of components for the NUBIRA/LACETTI vehicle.

When reference is made in this manual to a brand name, number, or specific tool, an equivalent product may be used in place of the recommended item.

All information, illustrations and specifications contained in this manual are based on the latest product information available at the time of publication approval. The right is reserved to make changes at any time without notice.

GM Daewoo Auto & Technology Co., Ltd.
Service Engineering Team
199-1 Cheong Cheon-Dong, Bupyeong-Gu, Incheon, Korea
Tel: 82-32-520-2737, 5752
Fax: 82-32-520-4808
E-mail: seoghi.han@gmdat.com
sanggoo.b.lee@gmdat.com

GM Daewoo Auto & Technology Co., Ltd.
All Rights Reserved

No part of this publication may be reproduced, stored in any retrieval system or transmitted, in any form or by any means, including but not limited to electronic, mechanical, photocopying, recording or otherwise, without the prior written permission of GM Daewoo Auto & Technology Co., Ltd.

Printed in the Republic of Korea

TABLE OF CONTENTS

Section 0B	General Information	Section 6C	Power Steering Gear
Section 1	Engine	Section 6E	Steering Wheel and Column
Section 1A	General Engine Information	Section 7	Heating, Ventilation, and Air Conditioning (HVAC)
Section 1C1	1.4L/1.6L DOHC Engine Mechanical	Section 7A	Heating and Ventilation System
Section 1C2	1.8L DOHC Engine Mechanical	Section 7B	Manual Control Heating, Ventilation, and Air Conditioning System
Section 1D	Engine Cooling	Section 7D	Automatic Temperature Control HVAC
Section 1E	Engine Electrical	Section 8	Restraints
Section 1F	Engine Controls	Section 8A	Seat Belts
Section 1G	Engine Exhaust	Section 8B	Supplemental Inflatable Restraints (SIR)
Section 2	Suspension	Section 9	Body and Accessories
Section 2A	Suspension Diagnosis	Section 9A	Body Wiring System
Section 2B	Wheel Alignment	Section 9B	Lighting Systems
Section 2C	Front Suspension	Section 9C	Horns
Section 2D	Rear Suspension	Section 9D	Wipers/Washer Systems
Section 2E	Tires and Wheels	Section 9E	Instrumentation/Driver Information
Section 3	Driveline/Axle	Section 9F	Audio Systems
Section 3A	Automatic Transaxle Drive Axle	Section 9G	Interior Trim
Section 3B	Manual Transaxle Drive Axle	Section 9H	Seats
Section 4	Brakes	Section 9I	Waterleaks
Section 4A	Hydraulic Brakes	Section 9J	Windnoise
Section 4B	Master Cylinder	Section 9K	Squeaks and Rattles
Section 4C	Power Booster	Section 9L	Glass and Mirrors
Section 4D	Front Disc Brakes	Section 9M	Exterior Trim
Section 4E1	Rear Disc Brakes	Section 9N	Frame and Underbody
Section 4E2	Rear Drum Brakes	Section 9O	Bumpers and Fascias
Section 4F	Antilock Brake System	Section 9P	Doors
Section 4G	Parking Brake	Section 9Q	Roof
Section 5	Transmission/Transaxle	Section 9R	Body Front End
Section 5A1	ZF 4HP16 Automatic Transaxle	Section 9S	Body Rear End
Section 5A2	AISIN Automatic Transaxle	Section 9T1	Remote Keyless Entry and Anti-Theft System
Section 5B	Five-Speed Manual Transaxle	Section 9T2	Immobilizer Anti-Theft System
Section 5C	Clutch		
Section 6	Steering		
Section 6A	Power Steering System		
Section 6B	Power Steering Pump		

GM DAEWOO PUBLICATION COMMENT FORM

Use this form to advise us of any errors you might find in this publication. We also welcome your suggestions that might help us improve GM Daewoo publications.

Publication that contains error:

Page number where the error appears:

Figure number where the error appears: _____

Vehicle application and system identification:

Describe the error found or your suggestion in detail. Please attach additional pages as necessary. Please attach a copy of illustrations that contain errors.

This image shows a single sheet of white paper with horizontal ruling lines. The lines are evenly spaced and run across the width of the page. There are no margins, text, or other markings on the paper.

From: Name

Address	Country
---------	---------

Signature _____ Date _____ Phone _____

Mail To: GM Daewoo Auto & Technology Co., Ltd.
Service Engineering Team
199-1 Cheong Cheon-Dong, Bupyeong-Gu,
Incheon, Korea

E-Mail : Seoghi.han@gmdat.com (S.H.Han) or Sanggoo.b.lee@gmdat.com (S.G.Lee)