




Gearshift Mechanism

Overhaul

NOTE:

- Inspect rubber parts for wear and damage when disassembling.
- Check that the new cotter pin is seated firmly.



A: SELF-LOCKING NUT
Replace.

6 x 1.0 mm
9.8 N·m (1.0 kgf·m, 7 lbf·ft)