



SERVICE BULLETIN

QUALITY INFORMATION ANALYSIS
OVERSEAS SERVICE DEPT. MITSUBISHI MOTORS CORPORATION

SERVICE BULLETIN		No.: ESB-98E00-012	
		Date: 1998-10-15	<Model> (EC,EXP) ECLIPSE (D30)
Subject: CHANGE IN YEAR MODEL FOR '99 ECLIPSE		<M/Y> 99-10	
Group: GENERAL		Draftno: 98SP040610	
INFORMATION	OVERSEAS SERVICE DEPT	 O. Kai - E.V.P. & G.M. After Sales Service Dept.	

1. Description:

This Service Bulletin informs you of change in year model for the 1999 ECLIPSE.

2. Applicable Manuals:

Manual	Pub. No.	Language	Page(s)
'96 ECLIPSE Workshop Manual	PWUE95E1	(English)	
	PWUS95E1	(Spanish)	
	PWUF95E1	(French)	
	PWUG95E1	(German)	
	PWUD95E1	(Dutch)	
	PWUI95E1	(Italian)	

3. Effective Date:

From the 1999 model

ECLIPSE

WORKSHOP MANUAL SUPPLEMENT

FOREWORD

This manual outlines changes in servicing procedures related to the chassis including vehicle inspections, adjustments and improvements in the newly equipped models.

Use the following manuals in combination with this manual as required

TECHNICAL INFORMATION MANUAL

WORKSHOP MANUAL

CHASSIS GROUP

ENGINE GROUP

PWEE □□□□

(Looseleaf
edition)

ELECTRICAL WIRING

BODY REPAIR MANUAL

PARTS CATALOGUE

All information, illustrations and product descriptions contained in this manual are current as at the time of publication. We however, reserve the right to make changes at any time without prior notice or obligation.



GROUP INDEX

General	00
Interior	52
Chassis Electrical	54
Heater, Air Conditioner and Ventilation.....	55

GROUP 00

GENERAL

VEHICLE IDENTIFICATION

MODEL

Model code	Engine model	Transmission	Fuel supply system
D3WAMNHSLF6	4G63 (1,991 mℓ)	F5M31 (2WD-5M/T)	MPI

4MB	M	N	D32	A	X	E	000001
1	2	3	4	5	6	7	8

V0204AA

CHASSIS NUMBER

The chassis number is stamped on the toeboard inside the engine compartment.

No.	Items		Contents
1	Mitsubishi Motor manufacturing of America, Inc.	-	-
2	Body style	M	2-door hatchback
3	Transmission type	N	5-speed manual
4	Development order	D32	1,997 mℓ petrol (DOHC, 2WD)
5	Sort	A	Passenger car
6	Model year	X*	1999
7	Plant	E	Mitsubishi Motor manufacturing of America, Inc.
8	Serial number	-	-

NOTE

*: Indicates change

GROUP 52A INTERIOR


AND GROUP 54 CHASSIS ELECTRICAL

GENERAL

OUTLINE OF CHANGES

- The centre air outlet assembly installation service point in the removal and installation procedures for the following parts has been deleted to correspond to the abolition of the cool air bypass lever.
- (1) GROUP 52A
 - Instrument panel
- (2) GROUP 54
 - Hazard warning lamp switch
 - rear window defogger switch

<Deleted>



INSTALLATION SERVICE POINT CENTRE AIR OUTLET ASSEMBLY INSTALLATION

- (1) Turn the cool air bypass lever of the centre air outlet assembly fully downwards.
- (2) pull the cool air bypass damper lever on the heater unit side all the way towards you, and then connect the cable to the lever pin.
- (3) Push the outer cable in the direction of the arrow so that there is no looseness, and then secure it with the clip.

GROUP 55

HEATER, AIR CONDITIONER AND VENTILATION

GENERAL

OUTLINE OF CHANGES

- The centre air outlet assembly cool air bypass lever has been no longer used.
- The centre air outlet assembly installation service point in the removal and installation procedures for the A/C switch has been deleted to correspond to the abolition of the cool air bypass lever. (Refer to GROUP 52A and 54.)

