




Fig. 74: Trunk Release Circuit

WARNING SYSTEMS