

TECHNICAL BULLETIN

Vehicle Model:

QQ

No: TB-T0032**Date:** July 20, 2006**Section:** Transmission**Title:**

Bulletin about QQ AMT Vehicle Transmission Clutch Self-detection

Affected range:

QQ AMT Vehicle

Description:

Recently, some dealers reflect that QQ AMT vehicle can't run correctly after being replaced electronic control parts (such as clutch or TCU) on transmission. Such problem can be solved by clutch self-detection.

Please see the following attachment for the detailed procedure about AMT transmission clutch self-detection.

Compiled by:
Nicholas Wang

Checked by:
Tony Gu

Approved by:
Frank Ouyang

Attachment:

Clutch Self-detection Flow Chart

