

SECTION 9G

BODY & ACCESSORIES (INTERIOR TRIM)

931. INSTRUMENT PANEL 9G – 3

932. MOLDING & SWITCH 9G – 7

933. INSTRUMENT PARTS 9G – 9


934. CONSOLE 9G –11

935. FRONT DOOR TRIM 9G –13

936. REAR DOOR TRIM 9G –15


938. PILLAR TRIM 9G –17

939. FLOOR CARPET 9G –19




INTERIOR TRIM – INSTRUMENT PANEL (931)					
NO.	OPERATION DESCRIPTION	OPERATION CODE	MODEL		
			S	N	L
1	LOCK, COMPARTMENT I/P – REPLACE	9310100	0.2	0.2	0.2
2	HINGE AND/OR STRIKER, COMPARTMENT I/P – ADJUST OR REPLACE	9310300	0.2	0.3	0.2
3	BOX, GLOVE – REPLACE	9310700	0.2	0.3	0.3
4	PANEL, CARRIER ASSEMBLY INSTRUMENT CONTROL – REPLACE INC : Enable and disable SIR system if nec. INC : Transfer of all nec. parts A – W/Passenger side air bag	9310900	2.1	2.5	2.5
		931090A	0.2	0.2	0.2
5	PANEL, SHROUD SIDE TRIM (KICK PAD) – REPLACE	Right 9311100	0.2	0.2	0.2
		Left 9311200	0.2	0.2	0.2
6	COVER, INSTRUMENT LOWER – REPLACE	9311400	0.2	0.2	0.3
7	COVER, BLANK – REPLACE	9311600	0.2	0.2	0.2
8	NOZZLE, VENTILATION CENTER – REPLACE	9311800	0.3	0.4	0.4
9	NOZZLE, VENTILATION – REPLACE	Left 9311900	2.1	0.6	2.7
		Right 9311910	2.1	0.6	2.7
		Both 9311920	2.1	1.0	2.7
10	NOZZLE, DEFROSTER – REPLACE	Right 9312100	—	0.3	0.2
		Left 9312200	—	0.3	0.2
		Both 9312300	—	0.5	0.3
11	KNEE BOLSTER – REPLACE	Right 9312400	0.4	0.4	0.4
		Left 9312500	0.4	0.4	0.4

NUBIRA / LACETTI , EVANDA




KALOS




INTERIOR TRIM – INSTRUMENT PANEL (931)

NO.	OPERATION DESCRIPTION	OPERATION CODE	MODEL		
			S	N	L
12	GRILLE, WINDSHIELD DEFROSTER – REPLACE				
		Right 9312600	—	—	0.2
		Left 9312700	—	—	0.2
		Both 9312800	—	—	0.3
13	BOX, COIN – REPLACE	9313000	0.2	—	0.2
14	COVER, PASSENGER AIR BAG (RHD ONLY) – REPLACE	9313200	0.3	—	—
15	COVER, A/C I/P – REPLACE	9314000	—	—	0.2
16	HOUSING, GLOVE BOX – REPLACE	9314100	—	—	0.4


EVANDA




NUBIRA / LACETTI



KALOS




INTERIOR TRIM – MOLDING & SWITCH (932)					
NO.	OPERATION DESCRIPTION	OPERATION CODE	MODEL		
			S	N	L
1	PLATE, I/P CLUSTER TRIM – REPLACE	9320100	—	0.3	0.6
2	SWITCH ASS'Y – REPLACE				
	Hazard Warning	9320300	0.2	0.2	0.4
	Fog Lamp	9320400	0.2	0.3	0.3
	Rear Defogger	9320450	0.3	0.3	0.3
3	SWITCH, ASS'Y – REPLACE				
	Anti-theft Lamp	9320500	0.3	0.3	0.3
4	CLOCK – REPLACE	9320600	0.2	0.2	0.4
5	SWITCH, ELECTRIC REMOTE MIRROR – REPLACE (ONE PIECE)	9320800	0.3	0.2	0.3
6	HOUSING, SWITCH – REPLACE	9321100	—	0.2	0.2
7	SWITCH, HEAD LAMP LEVELING – REPLACE	9321500	0.3	0.3	0.3
8	MOLDING, UPPER CLUSTER – REPLACE	9322400	0.2	—	—
9	MOLDING, LOWER CLUSTER – REPLACE	9322600	0.2	—	—
10	COVER, CLOCK – REPLACE	9322700	0.2	—	—
11	MOLDING, CENTER UPPER INSTRUMENT PANEL – REPLACE	9322800	0.2	0.2	—
12	SWITCH, DIMMER CONTROL – REPLACE	9322900	—	0.3	0.3
13	MOLDING, INSTRUMENT PANEL GARNISH – REPLACE	9323000	—	0.4	—




INTERIOR TRIM – INSTRUMENT PARTS (933)

NO.	OPERATION DESCRIPTION	OPERATION CODE	MODEL		
			S	N	L
1	PLATE, I/P CENTER TRIM – REPLACE	9330100	0.2	—	0.2
2	CUP, HOLDER, INSTRUMENT PANEL – REPLACE	9330300	2.0	—	—
3	ASH TRAY, I/P – REPLACE	9330500	0.2	0.6	—
4	BOX, DEPOSIT – REPLACE	9330900	0.2	0.2	0.2

NUBIRA / LACETTI , EVANDA




KALOS




INTERIOR TRIM – CONSOLE (934)					
NO.	OPERATION DESCRIPTION	OPERATION CODE	MODEL		
			S	N	L
1	CONSOLE ASSEMBLY, FRONT – REPLACE	Auto 9340100	—	0.5	0.5
		Manual 9340200	—	0.5	0.5
2	CONSOLE ASSEMBLY, REAR – REPLACE	Auto 9340400	—	0.4	0.4
		Manual 9340500	—	0.4	0.4
3	HOUSING, CIGARETTE LIGHTER – REPLACE	9340700	0.2	0.6	—
4	LIGHTER ASSEMBLY, CIGARETTE – REPLACE	9340900	0.3	0.2	0.2
5	CONSOLE ASSEMBLY – REPLACE	9341100	0.3	—	—
6	ASHTRAY, REAR – REPLACE	9341300	—	0.2	0.2
7	ASHTRAY, CONSOLE – REPLACE	9341400	—	—	0.2
8	HOUSING, CONSOLE ASHTRAY	9341440	—	—	0.3
9	HOLDER, CUP, CONSOLE – REPLACE	9341500	—	0.2	0.2
10	EXTENSION – CONSOLE, FRONT	Right 9341600	—	—	0.2
		Left 9341610	—	—	0.2
		Both 9341620	—	—	0.3
11	LAMP, ASHTRAY	9341650	0.2	0.2	0.3
12	JACK, EXTRA POWER SUPPLY (CONSOLE) – REPLACE	9341700	0.3	0.3	0.3
13	COVER, CONSOLE – REPLACE	9342400	—	0.3	0.3
14	BOX, REAR CONSOLE – REPLACE	9342500	—	0.2	0.2
15	LID, REAR CONSOLE – REPLACE	9342600	—	0.2	0.2

NUBIRA / LACETTI , EVANDA




KALOS




INTERIOR TRIM – FRONT DOOR TRIM (935)					
NO.	OPERATION DESCRIPTION	OPERATION CODE	MODEL		
			S	N	L
1	TRIM ASSEMBLY, FRONT DOOR – REPLACE				
		Right 9350100	0.3	0.3	0.4
		Left 9350200	0.3	0.3	0.4
		Both 9350300	0.5	0.5	0.7
2	HANDLE, FRONT DOOR INSIDE – REPLACE				
		Right 9350500	0.4	0.5	0.4
		Left 9350600	0.4	0.5	0.4
		Both 9350700	0.7	0.8	0.7
3	SEAL, FRONT DOOR TRIM	9350800	0.3	0.3	0.5
4	GRILLE, FRONT DOOR DEFROSTER – REPLACE	9351100	—	—	—
5	SWITCH, WINDOW LIFTER MAIN – REPLACE	9351300	0.3	0.3	0.3
		Passenger 9351310	—	0.3	0.3
6	CRANK, WINDOW LIFTER, FRONT – REPLACE				
		Right 9351500	0.2	—	—
		Left 9351600	0.2	—	—
		Both 9351700	0.3	—	—
7	GRILLE, FRONT SPEAKER – REPLACE				
		Right 9351800	—	—	0.4
		Left 9351900	—	—	0.4
		Both 9352000	—	—	0.5
8	WEATHER STRIP, FRONT DOOR INNER – REPLACE				
		Right 9353100	0.3	0.3	0.3
		Left 9353200	0.3	0.3	0.3
		Both 9353300	0.5	0.5	0.5
9	SWITCH, TRUNK OPEN – REPLACE	9353400	—	0.3	0.3



NUBIRA / LACETTI , EVANDA



KALOS




INTERIOR TRIM – REAR DOOR TRIM (936)					
NO.	OPERATION DESCRIPTION	OPERATION CODE	MODEL		
			S	N	L
1	TRIM ASSEMBLY, REAR DOOR – REPLACE				
		Right 9360300	0.3	0.3	0.4
		Left 9360400	0.3	0.3	0.4
		Both 9360500	0.5	0.5	0.7
2	HANDLE, REAR DOOR INSIDE – REPLACE				
		Right 9360700	0.4	0.4	0.4
		Left 9360800	0.4	0.4	0.4
		Both 9360900	0.7	0.7	0.7
3	SEAL, REAR DOOR TRIM – REPLACE	9361100	0.4	0.4	0.5
4	CRANK, WINDOW LIFTER – REPLACE				
		Right 9361300	0.2	0.2	—
		Left 9361400	0.2	0.2	—
		Both 9361500	0.3	0.3	—
5	SWITCH, WINDOW LIFTER REAR – REPLACE	9361700	0.3	0.3	0.3
6	WEATHER STRIP, REAR DOOR INNER – REPLACE				
		Right 9363100	0.3	0.3	0.3
		Left 9363200	0.3	0.3	0.3
		Both 9363300	0.5	0.5	0.5




INTERIOR TRIM – PILLAR TRIM (938)					
NO.	OPERATION DESCRIPTION	OPERATION CODE	MODEL		
			S	N	L
1	TRIM, CENTER PILLAR – REPLACE				
	Upper Right	9380100	0.2	0.3	0.3
	Lower Right	9380200	0.2	0.3	0.3
	TRIM, CENTER PILLAR – REPLACE				
	Upper Left	9380400	0.2	0.3	0.3
	Lower Left	9380500	0.2	0.3	0.3
2	COVER, ROCKER PANEL FRONT – REPLACE				
	Right	9380700	0.2	0.2	0.2
	Left	9380800	0.2	0.2	0.2
3	COVER, ROCKER PANEL REAR – REPLACE				
	Right	9381100	0.2	0.2	0.2
	Left	9381200	0.2	0.2	0.2
4	TRIM, BACK PANEL – REPLACE	9381400	0.2	0.2	0.2
5	MOLDING, WINDSHIELD GARNISH – REPLACE	9381600	0.2	0.2	0.2
6	TRIM, TRUNK – REPLACE	9381800	0.2	0.3	0.3
	TRIM, QUARTER (WAGON) – REPLACE	9381900	—	—	—
7	TRIM, SHROUD SIDE – REPLACE				
	Right	9382100	—	0.2	0.2
	Left	9382200	—	0.2	0.2
8	TRIM, C PILLAR – REPLACE	9382400	0.6	0.6	0.2
9	TRIM, REAR SIDE – REPLACE				
	Right	9382600	0.2	0.2	0.2
	Left	9382700	0.2	0.2	0.2

NUBIRA / LACETTI , EVANDA



KALOS



INTERIOR TRIM – FLOOR CARPET (939)					
NO.	OPERATION DESCRIPTION	OPERATION CODE	MODEL		
			S	N	L
1	CARPET, ONE PIECE FLOOR – REPLACE	9390100	1.4	1.5	1.3
2	CARPET, REAR COMPARTMENT FLOOR PANEL – REPLACE	9390300	0.2	0.2	0.2
3	COVER, SPARE TIRE – REPLACE	9390500	0.2	—	—
4	SHELF, LOAD COMPARTMENT – REPLACE	9390700	0.2	0.3	0.3
5	NET, LOAD COMPARTMENT – REPLACE	9390900	—	—	—
6	BOX, LOAD COMPART SIDE – REPLACE	9391100	—	—	—
7	PAD, FOOTREST – REPLACE	RHD 9391500	—	0.2	0.2
		LHD 9391600	—	0.3	0.3
8	TRAY, FRONT SEAT UNDER – REPLACE	9392000	—	0.4	—
9	COVER, REAR FLOOR DEPOSIT BOX – REPLACE	9392100	—	—	—